

M/053/0059
cc: Lynn

0005

UTAH 3600 COMPLIANCE INSPECTION REPORT

Contract: U-87390

Field Office: UT-100

Operator(s): Southwest Stone

Project name: Virgin Flagstone Negotiated Sale

Location: T41S R12W Sec 29 E1/2NESW; W1/2NWSE

Disturbance: Thirteen acres of the disturbed area reclaimed.

Hazardous Materials on Site: None/The site is pretty clean.

Comments: No activity. Flagstone pallets and fines stockpiled.

Recommended Action(s): None.

Photographs Taken: See Photographs below.


Inspector: Russell Schreiner

Date of Inspection: May 27, 2009

Reviewed by: _____ Date: _____
FM, St. George Field Office

RECEIVED

JUN 01 2009

DIV. OF OIL, GAS & MINING 0005




Overview looking northeast toward Virgin, showing the reclaimed area on the SW Stone negotiated contract site.



Overview looking southeast toward Gooseberry Mesa, showing the reclaimed area on the SW Stone negotiated contract site.



View of small older reclaimed section of about 3 acres and 2 to 3 years old that shows very little re-vegetation. Russian thistle, matchweed, filaree and a few sparse four-wing saltbush. A few palmer's penstemon in some areas.




Legend

Agricultural Research Station	National Park Service	Bankhead-Jones Land Use Lands
Bureau of Land Management	Indian Lands	State Lands
National Forest	Military Reservations	Private Lands
National Grasslands	National Wildlife Refuges	Water



United States Department of the Interior
Bureau of Land Management
Utah BLM Office

Map created on Apr 23, 2009



CAUTION:

Land ownership data is derived from less accurate data than the 1:24,000 scale base map. Therefore, land ownership should be shown for parcels smaller than 40 acres, and land ownership lines may have plotting errors due to source data.

No warranty is made by the Bureau of Land Management for the use of the data for purposes not intended by the BLM.